

From: [Guadalupe Quiroz](#)
To: [Mason, Steve](#)
Subject: Isit of tanks
Date: Monday, March 18, 2019 6:41:35 AM
Attachments: [image001.png](#)

Series 80

(Yubase 6) Tank 2 – manifold and roof
(Gasoline Blendstock) Tank 3- manifold
(Xylene) Tank 5 - both
(Gasoline Blendstock) Tank 6 - both
(Naphtha) Tank 8 - both original started
(SN 115) Tank 11 - both
(Toluene) Tank 13 -both
(Empty) Tank 9 - empty, manifold is engaged, and tank is collapsing
(Pyrolysis gas) about 4:30 a.m. Tank 14 – was on fire but put fire out



Guadalupe Quiroz
Emergency Response Work Leader
Texas Commission on Environmental Quality
5425 Polk Street, Ste. H
Houston, TX 77023
Phone 713.767.3608